



CODE ENFORCEMENT BOARD HEARING AGENDA

January 29, 2018 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Patrick McGee, Chair • Mark Booth, Vice Chair • Joan Hinton

- Lakhi Mohnani Peter Cooper Chris Evert William Marx •
 Robert Smith (alternate) Michael Madfis (alternate) Jonathan Keith (alternate)
- Board Attorney: Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

HEARING SCHEDULED

CASE NO: CE17100274

CASE ADDR: 3229 S ANDREWS AV

OWNER: MOMUNE LLC INSPECTOR: ROLDAN PEREZ

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. SEAL CUT AND RE-STRIPE WITHOUT PERMIT.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15100621

CASE ADDR: 2424 SE 17 ST # 309-B OWNER: APELQUIST, JARRETT P

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

- 1. ALTERATIONS MADE SUCH AS A KITCHEN REMODEL.
- 2. BATHROOM REMODEL.
- 3. WINDOWS REPLACED.
- 4. WASHER AND DRYER.

INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC (2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120268

CASE ADDR: 888 SE 3 AVE # 301A OWNER: 888 FORT LAUDERDALE LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO OFFICE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120269

CASE ADDR: 888 SE 3 AVE # 301B OWNER: 888 FORT LAUDERDALE LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO OFFICE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

THIS PROPERTY/CONDO OFFICE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE15120270

CASE ADDR: 888 SE 3 AVE # 400D

OWNER: 888 FORT LAUDERDALE LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO OFFICE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS

EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE17081353

CASE ADDR: 1600 W STATE ROAD 84 OWNER: WM C MORRIS POST #36

AMERICAN LEGION INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS PERFORMED WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE

VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17101607

CASE ADDR: 1400 NE 56 ST # 106
OWNER: DIXIE REALTY LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS BATHROOM RENOVATIONS, REMOVING AND REPLACING THE TILE BACKING BOARD IN BOTH BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. MECHANICAL ALTERATIONS MADE WITHOUT THE REOUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.
- 2. THE INSIDE A/C AIR HANDLER WAS REMOVED AND REPLACED.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.
- 2. KITCHEN: REMOVED AND REPLACED SINK AND FAUCET.
- 3. BATHROOM ONE WAS COMPLETELY REMODELED: REPLACED SHOWER WITH A PREFAB UNIT, REPLACED SHOWER VALVE, REPLACED TOILET, REPLACED VANITY SINK AND FAUCET.
- 4. BATHROOM TWO WAS PARTIALLY REMODELED: REPLACED SHOWER/TUB VALVE, REPLACED TOILET.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17101717

CASE ADDR: 4280 GALT OCEAN DR # 12N OWNER: LANDSKIND, EMMA & VIKTOR

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1 THE REMODELING OF THE KITCHEN WITHOU

1. THE REMODELING OF THE KITCHEN WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17101720

CASE ADDR: 4280 GALT OCEAN DR # 15N OWNER: ZHITNITSKY, BORIS & TATIANA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR DEMOLITION OF THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17101727
CASE ADDR: 3001 HARBOR DR

OWNER: RIVIERA RESORT CLUB DEV INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 116.2.1.2.1

A BUILDING SHALL BE DEEMED UNSAFE WHEN: THERE IS A FAILURE, HANGING LOOSE OR LOOSENING OF ANY SIDING, BLOCK, BRICK, OR OTHER BUILDING STRUCTURAL PARTS.

FBC(2014) 116.2.1.2.7

A BUILDING SHALL BE DEEMED UNSAFE WHEN: SWIMMING POOLS THAT CONTAIN STAGNANT WATER ARE DEEMED UNSANITARY AND DANGEROUS TO HUMAN LIFE AND PUBLIC WELFARE AND SHALL BE PRESUMED AND DEEMED UNSAFE.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

._____

CASE NO: CE17110021

CASE ADDR: 4010 GALT OCEAN DR # 907

OWNER: PELOSO, DEBORAH

PELOSO, DENNIS

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

I MADE MY INITIAL SITE VISIT TO THIS CONDO UNIT ON WEDNESDAY 11-01-2017 AT 3:30 PM. I WAS ESCORTED TO THE UNIT BY THE C.A.M. WHO PROVIDED ME ACCESS. MY FINDINGS WERE A FULL KITCHEN AND BATHROOM REMODEL IN PROGRESS. THE SCOPE OF WORK INCLUDES FRAMING, DRYWALL, ELECTRICAL, PLUMBING AND MECHANICAL. THERE WAS NO ONE WORKING ONSITE AT THIS TIME. THERE ARE NO ACTIVE PERMITS FOR THIS UNIT. I PLACED A STOP WORK ORDER AND TOOK PICTURES.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE

VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17110445

CASE ADDR: 2100 NE 39 ST # 407 OWNER: OBSZANSKI, ANDRZEJ

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS OF THE KITCHEN AND BATHROOM, ELECTRICAL AND PLUMBING WORK PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17071229
CASE ADDR: 1717 NE 16 AV
OWNER: BAKER & DIAZ LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS A FULL KITCHEN RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17071273
CASE ADDR: 2425 NE 25 PL
OWNER: BUDD, LISA J EST
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS CREATING AN ILLEGAL STUDIO UNIT WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16060534

CASE ADDR: 1104 NW 1 ST

OWNER: ELWELL, EDWIN C

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

THE FRONT OVERHANG OF THIS BUILDING IS UNDERGOING STRUCTURAL REPAIRS AND REROOF WITHOUT THE REQUIRED

PERMITS.

CASE NO: CE16080192

CASE ADDR: 2200 MARINA BAY DR E

OWNER: SPVEF-SKID LLC INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THERE IS AN OCCUPIED OFFICE TRAILER WITH A RAMP AND STAIRS ATTACHED ON THIS PROPERTY INSTALLED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.4

1. WATER HAS BEEN HOOKED UP TO THE OFFICE TRAILER WITHOUT A PERMIT.

2. THE OFFICE TRAILER SANITARY LINE HAS BEEN HOOKED UP TO AN ABOVE GROUND HOLDING TANK WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.5

ELECTRICAL POWER HAS BEEN HOOKED UP TO THE

OFFICE TRAILER ON THIS PROPERTY WITHOUT A PERMIT.

CASE NO: CE17030482

CASE ADDR: 3831 JACKSON BLVD

OWNER: RAYMOND, CHRISTOPHER MARICE

SMITH, TAMEQUA

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. FRONT FENCE/GATE INSTALLED WITHOUT PERMITS AND

INSPECTIONS.

CASE NO: CE17041535 CASE ADDR: 1243 NW 3 AVE

OWNER: MANJARRES, MARIA GABRIELA

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS, DOORS AND WOOD FENCE INSTALLED WITHOUT

PERMITS AND INSPECTIONS.

2. DOORS AND WINDOWS INSTALLED WITHOUT FIRST OBTAINING PERMITS AND INSPECTIONS.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED.

CASE NO: CE17060281
CASE ADDR: 5910 NE 18 AVE
OWNER: RAYYAN LLC
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS INSTALLED WITHOUT A PERMIT.

FBC(2014) 110.1

GENERAL CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION

PURPOSES UNTIL APPROVED.

WINDOWS INSTALLED WITHOUT AN INSPECTION.

.-----

CASE NO: CE17060477
CASE ADDR: 1609 NW 6 PL

OWNER: PROGRESSIVE INDUSTRIES LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS HAS BEEN INSTALLED IN THIS BUILDING WITHOUT INSPECTIONS.

FBC (2014) 110.1

GENERAL CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION WINDOWS AND DOORS

INSTALLED IN THIS BUILDING WITHOUT INSPECTIONS.

CASE NO: CE17080866
CASE ADDR: 1628 NE 4 PL
OWNER: NATION TRUST LLC
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

PLASTIC SHED WITH ELECTRICAL AND PLUMBING

CONNECTIONS INSTALLED AT THE REAR OF THE PROPERTY.

CASE NO: CE17060477
CASE ADDR: 1609 NW 6 PL

OWNER: PROGRESSIVE INDUSTRIES LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS HAS BEEN INSTALLED IN THIS BUILDING WITHOUT INSPECTIONS.

FBC(2014) 110.1

GENERAL CONSTRUCTION OR WORK FOR

WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF

THE JURISDICTION.

WINDOWS AND DOORS INSTALLED IN THIS BUILDING

WITHOUT INSPECTIONS.

._____

CASE NO: CE17060477
CASE ADDR: 1609 NW 6 PL

OWNER: PROGRESSIVE INDUSTRIES LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS HAS BEEN INSTALLED IN THIS BUILDING WITHOUT INSPECTIONS.

FBC(2014) 110.1

GENERAL CONSTRUCTION OR WORK FOR

WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF

THE JURISDICTION.

WINDOWS AND DOORS INSTALLED IN THIS BUILDING

WITHOUT INSPECTIONS.

._____

CASE NO: CE17060927
CASE ADDR: 1812 NW 13 CT
OWNER: CRUZ, FRANCES C
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS INSTALLED.

FBC(2014) 110.1

GENERAL CONSTRUCTION OR WORK FOR

WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. WORKING WITHOUT INSPECTIONS IS A VIOLATION.

CASE NO: CE17062413

CASE ADDR: 3034 NW 69 CT # 4D

OWNER: BONI FL LLC INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REAR SIDE OF ROOF TORN, STRIPPED AND DRYING WITHOUT A PERMIT.

2. WINDOWS AND DOOR INSTALLED WITHOUT A PERMIT.

FBC(2014) 110.1

GENERAL CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION

PURPOSES UNTIL APPROVED.

CASE NO: CE17080001 CASE ADDR: 1040 NE 7 AVE

OWNER: PRIVILEGE APARTMENTS LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 1029.4 EMERGENCY ESCAPE AND RESCUE

OPENINGS SHALL BE OPERATIONAL FROM THE INSIDE OF THE ROOM WITHOUT THE USE OF KEYS OR TOOLS. BARS, GRILLS, GRATES OR SIMILAR DEVICES ARE PERMITTED TO

BE PLACED OVER EMERGENCY ESCAPE AND RESCUE OPENINGS PROVIDED THE MINIMUM NET CLEARANCE

OPENING SIZE COMPLIES WITH SECTION 1029.2 AND SUCH DEVICES SHALL BE RELEASABLE OR REMOVABLE FROM THE INSIDE WITHOUT THE USE OF A KEY, TOOL OR FORCE GREATER THAN THAT WHICH IS REQUIRED FOR NORMAL OPERATION OF THE ESCAPE AND RESCUE OPENING. WHERE SUCH BARS, GRILLS, GRATES OR SIMILAR DEVICES ARE INSTALLED IN EXISTING BUILDINGS, SMOKE ALARMS SHALL BE INSTALLED IN ACCORDANCE WITH SECTION 907.2.11 REGARDLESS OF THE VALUATION OF THE

ALTERATION.

CASE NO: CE17062530
CASE ADDR: 2030 NE 31 AV
OWNER: CRICKETT, JOHN J

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BATHROOM REMODEL.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17010971
CASE ADDR: 516 NW 1 AVE

OWNER: 516 LLC

%CAROL D LENAHAN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTING DUMPSTER ENCLOSURE.

2. INTERIOR BUILD-OUT OF WALLS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF MINI-SPLIT A/C SYSTEM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS.
- 2. INSTALLATION OF RECEPTACLES.
- 3. INSTALLATION OF ELECTRICAL PANELS.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY

WITH NEC 406.4 (D) (1) THRU (D) (6) GFI?S REQUIRED AS PER NEC 108.8

OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS:

WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17070309 CASE ADDR: 2921 SW 19 AV

OWNER: KEYSTONE HALLS INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. RE-ROOFING AND HOT MOPPING WITHOUT A PERMIT.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17071043

CASE ADDR: 6250 N ANDREWS AVE # 25

OWNER: DOUBLE MOUNTAIN DEV VENTURES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. INTERIOR ALTERATIONS TO FLOOR PLAN.

2. INTALLED ELECTRICAL.

3. INSTALLED BATHTUBS

4. INSTALLED WATER HEATERS.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17071103
CASE ADDR: 407 SW 12 AVE
OWNER: GARRETT, ROBERT

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM REMODEL.

- 2. UPGRADE, ALTERATIONS AND REPLACEMENT OF SYSTEM COMPONENTS.
- 3. WOOD DECKING AT POOL AREA.
- 4. REPLCEMENT OF WOOD DECK AT FRONT PORCH.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17020146 CASE ADDR: 1545 NW 6 ST

OWNER: PERSAUD, BOODHWATTIE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING

PERMIT AND INSPECTIONS:
1. INSTALLATION OF SINKS.

2. INSTALLATION OF GAS LINES TO SERVICE GAS STOVES.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. ADDED OUTLETS.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH NEC 406.4 (D)(1) THRU (D)(6)
GFI?S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED FIRE SUPPRESSION SYSTEM WITH HOOD.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A OUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC (2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS PARCEL AND BUILDING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF BEAUTY SALON TO RESTAURANT WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE16021352 CASE ADDR: 1621 SW 25 ST

LAROCCA, DEBORAH L OWNER:

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT SCREENED PORCH STRUCTURE WITH A CORRUGATED ROOF.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16090703

CASE ADDR: 3058 N FEDERAL HWY

OWNER: OAKLAND CORNER CENTER LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THE FOLLOWING DESCRIBED WORK REQUIRES A DEMOLITION

PERMIT AND INSPECTIONS: 1. INTERIOR DEMOLITION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17040083
CASE ADDR: 2041 SW 32 TER
OWNER: CONSUEGRA, RAFAELA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. WINDOW AND DOOR INSTALLATIONS.
- 2. INSTALLATION OF MECHANICAL SPLIT A/C SYSTEM.
- 3. INSTALLATION OF MINI SPLIT MECHANICAL SYSTEM.
- 4. KITCHEN AND BATH REMODEL MAIN HOUSE.
- 5. BUILT AN APARTMENT AND BATH ON RIGHT SIDE OF SFR.
- 6. BLOCKED WINDOWS ON RIGHT AND LEFT ELEVATION OF SFR.
- 7. INSTALLED GLASS BLOCK ON LEFT ELEVATION.
- 8. INSTALLED YARD LIGHT AT FRONT AND BACK WITH NEW ELECTRICAL CIRCUITS.
- 9. INSTALLED TWO STORAGE SHEDS IN BACKYARD SETBACK.
- 10. ONE OF TWO STORAGE SHEDS CONVERTED TO LIVING SPACE WITH UTILITIES.
- 11. TWO SHEDS IN SETBACK.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

.....

CASE NO: CE17050489
CASE ADDR: 1206 NW 4 AV

OWNER: MASTER INVESTMENT PROPERTIES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. INSTALLATION OF WINDOW AT BACK ELEVATION.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY

REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND

ISSUANCE OF ALL AND ANY PERMITS AND/OR

DETERMINATION OF COMPLIANCE WITH THE FLORIDA

BUILDING CODE.

CASE NO: CE17051264 CASE ADDR: 1305 NW 15 CT

OWNER: MULLINGS, ROBERT S H/E

MULLINGS, JENNIFER ARLENE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. ADDED SHED TO EXISTING UTILITY BUILDING. 2. REPLACED FENCE ON WEST SIDE OF PARCEL.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17052136

CASE ADDR: 1064 CAROLINA AVE OWNER: PIERRE, JACQUES C

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ENCLOSED CARPORT.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17060766
CASE ADDR: 3326 NE 18 ST
OWNER: POLLOCK, JACOB

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REMODELED KITCHEN AND BATHROOM.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17060453 CASE ADDR: 1800 SE 24 AV

OWNER: FISETTE, GARY A EST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ROOF STRUCTURES DO NOT HAVE UPLIFT CONTINUITY TO FOUNDATION.
- 2. ELECTRICAL WORK WAS DONE WITH ADDED BREAKER PANELS AND CIRCUITS.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17060458 CASE ADDR: 1535 NW 10 AV

OWNER: WASHINGTON, JEANETTE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR ALTERATIONS AND REMODELLING.
- 2. CONSTRUCTED KITCHEN AND BATHROOM.
- 3. CONVERTED SFR TO DUPLEX.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS PARCEL AND BUILDING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SFR TO DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE17060261 CASE ADDR: 1041 NE 9 AVE

OWNER: SELF DIRECTED IRA SERVICES INC

JULIET A HORNER IRA 201315701

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTED AN ENCLOSED GARAGE.

2. BUILT FENCE.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17060963
CASE ADDR: 1410 NW 4 AVE
OWNER: PETIT, FRANCOIS

DIEUJUSTE, ST CHARLES

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURE BUILT WITHOUT PERMITS.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17061437
CASE ADDR: 1211 SW 31 AVE
OWNER: BELL, CAMILE R
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ENCLOSED WINDOW AT REAR ADDITION AND BUILT SHED WITHOUT PERMIT.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17061452

CASE ADDR: 3310 JACKSON BLVD

OWNER: MARTINEZ, REGINALDO & RUTH D

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

THE FOLLOWING MANNER, BUT NOT LIMITED TO 1. CONCRETE PATIO SLAB WITHOUT PERMIT.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17062111
CASE ADDR: 2667 NE 32 ST
OWNER: BARMER LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTION ALTERATIONS TO THE INTERIOR OF THE BUILDING.

- 2. MODIFIFICATION OF EQUIPMENT AND BUILDING SYSTEMS SERVICING THE STRUCTURE.
- 3. BUILT ROOF STRUCTURE AT THE REAR POOL DECK AREA.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17062112
CASE ADDR: 2640 NE 32 ST
OWNER: BARMER LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONSTRUCTION ALTERATIONS TO THE INTERIOR OF THE BUILDING.
- 2. MODIFIFICATION OF EQUIPMENT AND BUILDING SYSTEMS SERVICING THE STRUCTURE.

THIS PROPERTY IS BEING USED AS A HOTEL/MOTEL FACILITY IN CONJUNCTION WITH 2648-2667 NE 32 ST.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17062113
CASE ADDR: 2648 NE 32 ST
OWNER: BARMER LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTION ALTERATIONS TO THE INTERIOR OF THE BUILDING.

2. MODIFICATION OF EQUIPMENT AND BUILDING SYSTEMS SERVICING THE STRUCTURE.

THIS PROPERTY IS BEING USED AS A HOTEL/MOTEL FACILITY IN CONJUNCTION WITH 2640-2667 NE 32 ST.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16121947

CASE ADDR: 5411 NE 18 AVE # 4
OWNER: WALTERS, ELMORE
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDITION BEING BUILT IN THE REAR OF THE PROPERTY.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17010269
CASE ADDR: 3100 NE 44 ST
OWNER: RIZZO, SUSAN V
PAUSE REV LIV TR

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. NEW ELCTRICAL OUTLETS IN BACK PATIO.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE

PERMITTING PROCESS.

CASE NO: CE17021437 CASE ADDR: 4521 NE 21 AVE

OWNER: CORAL RIDGE LANDINGS CONDO ASSN INC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. FENCE INSTALLATION WITHOUT PERMIT.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17031412 CASE ADDR: 1117 NW 7 TER

OWNER: UTHE, SEAN MICHAEL INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW METAL/WOOD FENCE BEING INSTALLED ON FRONT

YARD.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. NEW METAL/WOOD FENCE BEING INSTALLED IN FRONT YARD.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17040532 CASE ADDR: 1820 NE 59 CT

OWNER: ANIBAL RIPOLL/NIRACI LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. NEW PAVER DRIVEWAY INSTALLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17041700 CASE ADDR: 621 SE 1 AVE

OWNER: FIRST STREET HOLDINGS LLC

HALL, JOHN T

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. STRIPING INSTALLED ON PARKING LOT.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17050053 CASE ADDR: 2808 SW 7 ST

OWNER: SERRANO, GILFREDO H/E

ESTEVEZ, CONCEPCION

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. TWO NEW CONCRETE DRIVEWAYS INSTALLED.

2. NEW LIVING AREA ERECTED ON SE CORNER OF THE PROPERTY ENCROACHING ON THE SETBACK.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17051543 CASE ADDR: 1816 SW 11 ST

OWNER: COMMUNITY 8 PROPERTIES LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WALL MOUNTED A/C UNIT.

2. SHED INSTALLED IN BACK YARD.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17051886 CASE ADDR: 1643 NW 10 AVE

OWNER: HSBC BANK USA NA TRSTEE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW WOOD FENCE INSTALLED ON BOTH SIDES OF FRONT ELEVATION OF PROPERTY.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION. INSPECTIONS PRESUMING TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION SHALL NOT BE VALID. IT SHALL BE THE DUTY OF THE PERMIT APPLICANT TO CAUSE THE WORK TO REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES. NEITHER THE BUILDING OFFICIAL NOR THE JURISDICTION SHALL BE LIABLE FOR EXPENSE ENTAILED IN THE REMOVAL OR REPLACEMENT OF ANY MATERIAL REQUIRED TO ALLOW INSPECTION.

CASE NO: CE17052178
CASE ADDR: 540 SW 11 AV

OWNER: SCHLOSSER, STEVEN & FIONA

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. UNPERMITTED ATTACHMENT TO FENCE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. EXTERIOR "ALGAE FARM"

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17052208

CASE ADDR: 2510 DEL LAGO DR OWNER: MALVASIO, JOSEPH

MALVASIO REAL ESTATE TR

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW WOOD DECK DOCK BEING INSTALLED ON THE BACK

OF PROPERTY.

FBC (2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION. INSPECTIONS PRESUMING TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION SHALL NOT BE VALID. IT SHALL BE THE DUTY OF THE PERMIT APPLICANT TO CAUSE THE WORK TO REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES. NEITHER THE BUILDING OFFICIAL NOR THE JURISDICTION SHALL BE LIABLE FOR EXPENSE ENTAILED IN THE REMOVAL OR REPLACEMENT OF ANY MATERIAL REQUIRED TO ALLOW INSPECTION.

CASE NO: CE17060215 CASE ADDR: 2501 SW 29 WAY

OWNER: LEIVA, STEPHANIE S & CESAR

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. A NEW GAZEBO INSTALLED ON THE NORTH SIDE OF

PROPERTY.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17060541 CASE ADDR: 17 SW 24 ST

OWNER: GOLD TREE ENERGY LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. AWNING STRUCTURE INSTALLED ON EAST SIDE OF THE PROPERTY.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 101.4.4.1

RAINWATER OR OTHER LIQUID WASTES FROM ANY PREMISES SHALL BE DISPOSED OF WHERE SAME ORIGINATES AND/OR FALLS. THE DISPOSAL OF ANY RAINWATER OR OTHER LIQUID WASTES BY CAUSING OR ALLOWING SAME TO BE DISPOSED OF OR FLOW ON OR ACROSS ANY ADJOINING PROPERTY OR SIDEWALK, EITHER PUBLIC OR PRIVATE, SHALL BE DEEMED A NUISANCE, AND SHALL BE CORRECTED BY PROPERLY DISPOSING OF SAME.

CASE NO: CE17061475 CASE ADDR: 2886 NE 25 ST

OWNER: YUZ, MICHAEL & ELAINE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. EXISITNG DOCK WAS DEMOLISHED.

2. FLOATING DOCK INSTALLED.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17062711 CASE ADDR: 1309 NW 8 AV

OWNER: EL MAR INVESTMENTS LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW WOOD FENCE INSTALLED IN FRONT ELEVATION.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17070040

CASE ADDR: 1001 ARIZONA AVE
OWNER: JACKSON, ROSELIND Y
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. SEPTIC TANK INSTALLED ON EAST SIDE OF PROPERTY.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17071228 CASE ADDR: 1027 NE 13 AV

OWNER: NIKAJ, ESMERALDA & NESTI

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(204) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CARPORT ENCLOSED.
- 2. WINDOW ENCLOSURES AND WINDOW REPLACEMENT.
- 3. NEW CONCRETE SLAB ON BACKYARD.
- 4. NEW CONCRETE DRIVEWAY.
- 5. RELOCATION OF A/C UNIT.
- 6. PLUMBING INSTALLATION ON NEW CONCRETE SLAB.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17080023

CASE ADDR: 1901 N OCEAN BLVD

OWNER: THE SHORE CLUB CONDO ASSN INC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. RAINWATER PIPES WERE REDIRECTED TO THE BACK OF THE BUILDING INTO A GRASS AREA THAT DRAINS TO THE

BACK STREET.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17082234 CASE ADDR: 2090 NE 55 CT

OWNER: PARACHA INVESTMENTS LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR FRAMING.

- 2. ROOF STRUCTURE REPAIRS.
- 3. KITCHEN AND BATHROOMS REMODELING.
- 4. A/C DUCT WORK.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE13051997 CASE ADDR: 1515 NW 7 AVE

OWNER: YUTHASUNTHORN, CHANCE YUTHASUNTHORN, SIRILUK

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE

FOLLOWING MANNER WITHOUT A PERMIT:
1. NEW WINDOWS HAVE BEEN INSTALLED.

2. A KITCHEN REMODELING PROJECT IS IN PROGRESS.

3. A BATHROOM REMODELING PROJECT IS IN PROGRESS.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED BY THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14031507 CASE ADDR: 416 SW 11 CT

OWNER: REYNOLDS, STUART L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

- 1. THE PROPERTY OWNER HAS CONVERTED THIS SINGLE FAMILY HOUSE INTO A DUPLEX RENTING OUT THE BACK AND FRONT TO TWO DIFFERENT FAMILIES. THEY HAVE ENCLOSED THE CARPORT AND HALLWAY LEADING TO ONE PART OF THE HOUSE TO CREATE THE NEW FLOOR PLAN.
- 2. THEY HAVE ADDED ELECTRIC OUTLETS AND PLUMBING FIXTURES IN THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THE CARPORT HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION CLASS U (UTILITY) TO R-3 (LIVING SPACE) WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

._____

CASE NO: CE14051440

CASE ADDR: 1663 NW 15 TER

OWNER: ALLADIN, VANEL

INSPECTOR: JOSE ABIN,

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. THE DWELLING'S OPENINGS WERE BOARDED AND THE WOOD HAS BEEN REMOVED.
- 2. NEW WINDOWS AND EXTERIOR DOORS WERE INSTALLED ON THEM.
- 3. INTERIOR UPGRADE INSIDE THE KITCHEN AND BATHROOMS AREAS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15121310

CASE ADDR: 4100 N FEDERAL HWY
OWNER: 4100 FEDERAL HWY LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. KITCHEN LAYOUT RECONFIGURED FROM ORIGINAL FLOORPLAN.
- 2. DINING ROOM LAYOUT CHANGED.
- 3. INSTALLED CANOPY ON NORTH SIDE OF BUILDING.
- 4. RECONFIGURED STORAGE AREAS.
- 5. BUILT A DECORATIVE STRUCTURE WITHIN THE DINING/BAR AREA.
- 6. 3 SIGNS INSTALLED USING THE EXISTING ELECTRICAL.

FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REMOVED BAR AREA AND SINKS.
- 2. REMOVED WALL SINKS AT ENTRY TO KITCHEN.

FBC (2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDED NEW PLUMBING AND FIXTURES. PENETRATIONS THROUGH EXTERIOR WALL TO SERVICE NEW PLUMBING ALTERATIONS.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDED NEW ELECTRICAL. NEW CONDUITS VISIBLE.
PENETRATIONS THROUGH EXTERIOR WALL TO SERVICE NEW
ELECTRICAL INSTALLATIONS. ELECTRICAL ALTERATIONS
TO THE BAR AREA.

FBC(2014) 105.3.1.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS FROM A CERTIFIED AND LICENSED DESIGN PROFESSIONAL ADDRESSING THE ENTIRE EXISTING STRUCTURE AND SYSTEMS.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. STORAGE FREEZERS HAVE BEEN ALTERED.
- 2. NEW MECHANICAL INSTALLATION UNDER CANOPY ON NORTH SIDE OF BUILDING.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF EXTERIOR DOORS AT NORTH SIDE OF BUILDING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16071549
CASE ADDR: 942 NW 13 ST

OWNER: KRAVICH, JOE & RANIT

MALMAZADA, S & ULNER, BARUCH

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REBUILT ROOF STRUCTURE REQUIRING ENGINEERING.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY

DESIGN PROFESSIONAL.

ROOF STRUCTURE REPAIRS WILL REQUIRE DOCUMENTS PREPARED, SIGNED AND SEALED BY A DESIGN

PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVER-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16101307
CASE ADDR: 600 NW 18 ST
OWNER: KAAREFL CORP
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 1029.4

THIS BUILDING HAS BEEN ILLEGALLY ALTERED FOLLOWING

MANNER, BUT NOT LIMITED TO:

1. PLACED SHUTTERS AND WOOD PANELS ON A PERMANENT BASIS OVER WINDOWS.

2. PERMANETLY SCREWED SHUT WINDOW.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A SCREEN ENCLOSURE ON THE RIGHT ELEVATION.

- 2. BUILT INTERIOR PARTITIONS TO DIVIDE THE EAST APARTMENT INTO 2 UNITS.
- 3. ADDED 2 BATHROOMS IN UTILITY ROOMS OF EACH UNIT.
- 4. ADDED KITCHEN AT EAST SIDE UNIT.
- 5. BLOCKED WINDOWS WITH WOOD PANELS AT SEVERAL LOCATIONS OBSTRUCTING EMERGENCY ESCAPE.
- 6. SCREWED SHUT A WINDOW OBSTRUCTING EMERGENCY ESCAPE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF 2 MECHANICAL SPLIT A/C SYSTEMS. SYSTEM NUMBER 1 DATED 2004. SYSTEM NUMBER 2 DATED 2016.
- 2. INSTALLED DUCT WORK TO SERVICE THE 2 A/C SYSTEMS.
- 3. THIRD ILLEGAL UNIT DOES NOT HAVE THERMOSTAT.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLED WINDOW AT BATHROOM OF UNIT W.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLED WOOD FENCE AND THE PERMIT WAS VOIDED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED WATER HEATER.
- 2. PLUMBING FOR 2 ILLEGALLY ADDED BATHROOMS.
- 3. PLUMBING FOR CLOTHES WASHER.
- 4. PLUMBING FOR ILLEGALLY ADDED KITCHEN.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. CIRCUITS ADDED TO SERVICE CLOTHES DRYER.
- 2. CIRCUIT ADDED TO SERVICE CLOTHES WASHER.
- 3. CIRCUITS ADDED TO SERVICE WATER HEATER.
- 4. CIRCUITS ADDED TO SERVICE 2 AIR CONDITIONERS.
- 5. CIRCUIT ADDED TO SERVICE ILLEGAL KITCHEN.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF DUPLEX TO TRIPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

1. EAST UNIT WAS CONVERTED INTO 2 APARTMENTS.

NEC(2005) 110.12

OPEN PORT AT ELECTRICAL CIRCUIT PANEL.

NEC(2005) 110.27

- (A) LIVE PARTS GUARDED AGAINST ACCIDENTAL CONTACT. EXCEPT AS ELSEWHERE REQUIRED OR PERMITTED BY THIS CODE, LIVE PARTS OF ELECTRICAL EQUIPMENT OPERATING AT 50 VOLTS OR MORE SHALL BE GUARDED AGAINST ACCIDENTAL CONTACT BY APPROVED ENCLOSURES OR BY ANY OF THE FOLLOWING MEANS:
- 1. BY LOCATION IN A ROOM, VAULT, OR SIMILAR ENCLOSURE THAT IS ACCESSIBLE ONLY TO QUALIFIED PERSONS.
- 2. ELECTRICAL PANEL LOCATED IN ILLEGAL BATHROOM OVER TOILET BOWL.

CASE NO: CE17060974
CASE ADDR: 451 NW 23 AVE

OWNER: SUMMER LAKE VILLAS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 1013.2

THE GUARDS ON THE SECOND FLOOR ARE DAMAGED AND MISSING SLATS AND THE OPENINGS ARE BEYOND THE MINIMIUM ALLOWABLE PRESENTING A LIFE AND SAFETY

HAZARD.

CASE NO: CE17041567

CASE ADDR: 200 S ANDREWS AVE # 603

OWNER: G & G INSURANCE ADJUSTERS INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

ON 04/28/2017 DURING SITE INSPECTION IT WAS

DISCOVERED THAT UNIT 603/602 PER VERBAL STATEMENT

MADE BY PROPERTY MANAGER.

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. SEPARATED UNIT 603 AND 604 AND INSTALLED TENANT SEPARATION FIRE BARRIER WITHOUT PERMIT AND DRAWINGS FROM A DESIGN PROFESSIONAL.

2. ELECTRICAL BREAKER PANEL MISSING IN UNIT 603.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS

CASE NO: CE17021462

CASE ADDR: 3161 RIVERLAND RD OWNER: FUNDING REALTY LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BUILT 2 WOOD DECKS.
- 2. ROOF STRUCTURE AT BACK ELEVATION.
- 3. REPAIR OF CABLE END WHERE A/C UNIT WAS REMOVED.
- 4. KITCHEN REMODEL REQUIRING BUILDING PERMIT.
- 5. INSTALLED MECHANICAL CENTRAL A/C SYSTEM.
- 6. ELECTRICAL CIRCUITS FOR A/C SYSTEM.
- 7. ELECTRICAL FOR KITCHEN AND PLUMBING REWIRE.
- 8. PLUMBING FIXTURES IN KITCHENS AND BATHROOMS.
- 9. LAWN SPRINKLER SYSTEM.
- 10. REPLACED POOL PUMP.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16120647 CASE ADDR: 1601 NW 11 CT

OWNER: EDEN HOUSE PROPERTY LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ENCLOSED CARPORT INTO LIVING SPACE.
- 2. BUILT ENCLOSURE FOR WATER HEATER.
- 3. CLOSED OPENINGS WHERE A/C UNITS WERE REMOVED.
- 4. WALL ENCLOSING CARPORT THAT HAD BEEN BLOWN OUT HAS BEEN REBUILT.
- 5. CONSTRUCTION OF HALF BATH.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.
- 3. INSTALLATION OF EXHAUST VENT IN WATER CLOSET.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WATER HEATER.
- 2. REPLACED FIXTURES IN LAUNDRY AREA.
- 3. REPLACEMENT OF BATHROOM AND KITCHEN FIXTURES.
- 4. INSTALLATION OF WASTELINE FOR HALF BATH.
- 5. INSTALLATION OF WATER SUPPLY LINES.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF CIRCUITRY FOR SPLIT A/C MECHANICAL SYSTEM.
- 2. INSTALLATION OF POTLETS.
- 3. INSTALLATION OF EXTERIOR LIGHTING.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH NEC 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16121959
CASE ADDR: 1524 SW 18 TER
OWNER: MINEO, MARK

MINEO, STEPHANIE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONSTRUCTED 3RD BEDROOM ADDITION CHANGING FLOOR PLAN FROM A 2 BEDROOM 1 BATH TO A 3 BEDROOM 2 BATH.
- 2. CONSTRUCTED ROOF OVER FRONT PORCH.
- 3. ENCLOSED CARPORT.
- 4. CONSTRUCTED STORAGE ATTIC IN ILLEGALLY ENCLOSED CARPORT.
- 5. CONSTRUCTED KITCHEN ADDITION.
- 6. INSTALLED HURRICANE STORM PANELS.
- 7. REPLACED FRONT DOOR.
- 8. INSTALLED SGD TO ENCLOSED SCREENED SUNROOM.
- 7. ALTERING, MODIFYING AND NEW WORK IN THE BUILDING SYSTEM REQUIRING PERMITS FROM SEVERAL DISCIPLINES.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16122275

CASE ADDR: 2649 GULFSTREAM LN

OWNER: GLIDDEN, TIMOTHY J & LISA C

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR RENOVATIONS.

- INSTALLED TILE BACKER IN KITCHEN FOR BACKSPLASH.
- 3. INSTALLED TILE BACKER IN BATHROOM WET AREAS.
- 4. ENCLOSED CARPORT.
- 5. REAR PORCH ROOF HAS NOT BEEN INSTALLED TO CODE AND REQUIRES ENGINEERING.

- 6. INSTALLED PAVERS AT REAR PORCH IN EXCESS OF 200 SQUARE FEET.
- 7. REBUILT DOCK.
- 8. INSTALLED NEW EXTERIOR DOORS.
- 9. CLOSED WINDOWS ON EXTERIOR WALL ENVELOPE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED SPLIT CENTRAL A/C SYSTEM.
- 2. INSTALLED NEW KITCHEN EXHAUST HOOD.
- 3. INSTALLED MECHANICAL VENTILATION IN BATHROOMS.
- 4. INSTALLED DUCT WORK FOR CENTRAL A/C SYSTEM.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS FOR GLAZED OPENINGS:

- 1. INSTALLED NEW WINDOWS.
- 2. INSTALLED NEW GLAZED DOORS.
- 3. INSTALLED NEW SLIDING GLASS DOORS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED NEW KITCHEN FIXTURES.
- 2. INSTALLED NEW BATHROOM FIXTURES.
- 3. INSTALLED NEW WATER HEATER.

FBC(2014) 105.3.1.4.5

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. WIRED NEW CIRCUITS FOR LIGHTING.
- 2. NEW CIRCUITS TO SERVICE CENTRAL A/C.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH NEC 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPE OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16121142
CASE ADDR: 3001 SE 6 AVE
OWNER: ROSSEL GROUP LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 1029.1

POSSIBLE BLOCKAGE OF EMERGENCY ESCAPE AND RESCUE OPENING BY THE ILLEGAL INSTALLATION OF A WATER HEATER IN FRONT OF A WINDOW.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURALLY MODIFYING DOOR OPENING ON EAST ELEVATION OF STRUCTURE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. THE INSTALLATION OF A MINI-SPLIT AIR-CONDITIONING SYSTEM.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF DOOR ON EAST SIDE OF STRUCTURE.
- 2. WINDOWS HAVE BEEN REPLACED.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF A WOOD FENCE ON THE EAST SIDE OF THE PARCEL.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF GAS WATER HEATER ON THE SOUTH SIDE. WATER HEATER IS SITTING DIRECTLY ON THE GROUND, TPR VALVE IS NOT EXTENDED, THE VENT IS DISPLACED AND UNIT IS IN FRONT OF WINDOW POSSIBLY BLOCKING EMERGENCY ESCAPE OPENING.
- 2. INSTALLATION OF GAS LINES TO SERVICE WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF BREAKER PANEL.
- 2. INSTALLATION OF A HARDWIRED CCTV SYSTEM.
- 3. INSTALLATION OF LIGHTING CIRCUITS.

FBC(2014) 110.2

THE BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17050290 CASE ADDR: 2005 NW 13 AV

OWNER: JONES, PERRONE & BENITA A

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 111.1.1

PERMIT 04112039 WAS FINALED ON 11/21/2016. UNDER THE TERMS OF THE PERMIT A CERTIFICATE OF OCCUPANCY

IS REQUIRED. SAID CERTIFICATE HAS NOT BEEN

OBTAINED AND THE PERMITTED WORK IS BEING ILLEGALLY

OCCUPIED.

CASE NO: CE17050468 CASE ADDR: 1600 SE 15 ST

OWNER: PLAZA 15 CONDO ASSN INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPAIR AND RESTORE DEMISING WALL COMMON TO UNIT 408 AND 410 DUE TO WATER DAMAGE.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17050759
CASE ADDR: 5541 NE 26 AVE

OWNER: MALDONADO, ALEXANDRE

MALDONADO, PATRICIA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. EXTERIOR ALTERATIONS MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16121219
CASE ADDR: 2733 NE 25 PL
OWNER: MARTELLO, REGINA

MORAIS, NUNO

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR DEMOLITION AND ALTERATIONS OF INTERIOR WALLS, MECHANICAL, ELECTRICAL AND PLUMBING WITHOUT

THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17032764

CASE ADDR: 4100 GALT OCEAN DR # 305

OWNER: CANNATARO, FRANCESCO

MARCHESE, PAULA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITH THE COMPLETE KITCHEN REMODEL.

2. TWO BATHROOMS REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC (2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17041396 CASE ADDR: 1732 NE 16 TER

OWNER: ANKEISTE HOLDINGS LTD

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS AND REMODELING PERFORMED

WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16111476

CASE ADDR: 2309 BARCELONA DR
OWNER: LIMA FAM TR ETAL

%ANTHONY LIMA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16091879

CASE ADDR: 4280 GALT OCEAN DR # 10J

OWNER: PORTER, GEORGE E

RITZ, MELINDA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. THE INTERIOR DEMOLITION OF WALLS, ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16100035

CASE ADDR: 2841 N OCEAN BLVD # 1508

OWNER: LOSE, JOHN J INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE KITCHEN AND BATHROOMS BEING REMODELED.
- 2. FRAMING AND DRYWALL THE CEILINGS IN THE KITCHEN AND BATHROOM.
- 3. CONVERTING A BATHTUB TO A SHOWER COMPROMISING THE FIREWALL AND THE PLUMBING PIPE SLAB PENETRATIONS.

ALL WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16090154

CASE ADDR: 1509 N FTL BEACH BLVD

OWNER: NUCCI, MARY J H/E

NUCCI, DANIELLE W

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF A CARPORT AND ROOF STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

CASE NO: CE16090595
CASE ADDR: 3134 NE 9 ST
OWNER: 3134 NE 9TH LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS INTERIOR DEMOLITION AND INTERIOR REMODELING INVOLVING STRUCTURAL, ELECTRICAL, MECHANICAL AND PLUMBING PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091319
CASE ADDR: 307 NE 23 AV

OWNER: WALTER A CROWELL TR

CROWELL, WALTER A TRSTEE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE INSTALLATION OF AN OUTDOOR KITCHEN STRUCTURE BUILT WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE INSTALLATION OF A GAS LINE INSTALLED FOR AN OUTDOOR KITCHEN WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17070987

CASE ADDR: 4250 GALT OCEAN DR # 3E OWNER: PAPRANIKU, DESHIRA & OLIVER

PAPRANIKU, MUZUYEN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS DEMOLITION, ELECTRICAL AND REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15092003 CASE ADDR: 1824 SE 1 AV

OWNER: KIENZLE, ROBERT F &

KIENZLE, LYBBI

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. AN INTERIOR ALTERATION HAS SUB-DIVIDED THIS SINGLE FAMILY RESIDENCE INTO AN ILLEGAL DUPLEX WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 2. WINDOWS WERE ALSO REMOVED AND REPLACED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15092005

CASE ADDR: 1800 N ANDREWS AVE # 05K
OWNER: A & H LUTHY REV LIV TR
LUTHY, PETER TRSTEE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED:

1. THE COMPLETE DEMOLITION OF THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS HAD PLUMBING ALTERATIONS PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVAL OF PLUMBING FIXTURES IN THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS HAD ELECTRICAL ALTERATIONS PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL OF THE CIRCUITS IN THE ELECTRICAL PANEL AND THE REMOVAL OF ALL THE ELECTRICAL DEVICES THROUGHOUT THIS CONDO UNIT WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120539
CASE ADDR: 3020 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL.
- 3. REBUILDING EXTERIOR STAIRS AND DECKS.
- 4. REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING COMPLETELY REMODELED. REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK IS BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK IS BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16011006

CASE ADDR: 2724 NE 15 ST

OWNER: 2724 NE 15 LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

._____

CASE NO: CE16011026
CASE ADDR: 1009 NE 17 CT
OWNER: CONROY, KYLE
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS PROPERTY WAS ORIGINALLY PERMITTED AS A TWO FAMILY DWELLING AND WAS ILLEGALLY CONVERTED IN A TRIPLEX UNIT WITHOUT THE PROPERTY CERTIFICATE OF OCCUPANCY. THERE HAS BEEN EXTENSIVE REMODELING WORK DONE ON THIS BUILDING WHICH INCLUDES BUT IS NOT LIMITED TO WINDOWS AND DOORS REPLACED, KITCHEN AND BATHROOM REMODELED, LAYOUT OF THE BUILDING HAS BEEN ALTERED.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE:

A. REMODELING KITCHENS, BATHROOMS, REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE:
A. ELECTRICAL PANELS REPLACED, DISCONNECTS
INSTALLED, ELECTRICAL OUTLETS, SWITCHES, DEVICES
REMOVED, REPLACED OR RELOCATED WITHOUT THE
REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITH REMOVING AND REPLACING THE A/C UNITS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE16030745
CASE ADDR: 2200 NE 52 CT
OWNER: JAOUADI, OUALID
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR AND EXTERIOR ALTERATIONS INCLUDING THE KITCHEN, BATHROOMS, WINDOWS AND DOORS INSTALLED WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

._____

CASE NO: CE16050869

CASE ADDR: 5100 BAYVIEW DR # 106
OWNER: SPECIALE, MICHAEL P
SPECIALE, SUSANNE A

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNITS' MASTER BATHROOM HAS BEEN ALTERED

WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS DEMOLITION, FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNITS' MASTER BATHROOM HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNITS' MASTER BATHROOM HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS CONDO UNITS' MASTER BATHROOM HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES OR POSSIBLY FOUR TIMES THE FEE UNDER SECTION 9-47 THAT WILL APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16110818
CASE ADDR: 1601 NW 11 AVE

OWNER: MALATESTA, MARIA PIERINA

SOTTER, PABLO O

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

RECEIVED EMAIL REGARDING WORK BEING DONE AT THIS LOCATION WITHOUT THE REQUIRED PERMITS:

- 1. THE KITCHEN AND BATHROOMS HAVE BEEN REMODELED.
- 2. NEW TILE BACKER AND DRYWALL INSTALLED.
- 3. A NEW DOOR OPENING HAS BEEN CUT INTO AND A NEW DOOR INSTALLED IN THE REAR BEDROOM WALL GOING TO THE PATIO.

FBC(2014) 105.3.1.4.15

2 WINDOWS ON THE REAR PATIO HAVE BEEN REPLACED.

FBC(2014) 105.3.1.4.18

THE WOOD FENCE AND GATE ON THE NORTH SIDE OF THIS PROPERTY HAS BEEN REPAIRED AND NEW FACE BOARDS REPLACED.

FBC(2014) 105.3.1.4.19

THE SCREEN ENCLOSURE AT THE REAR PATIO HAS BEEN REPLACED.

CASE NO: CE16051684
CASE ADDR: 1447 NW 6 ST
OWNER: JAMES, LOUIS
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

SENT TO THIS LOCATION BY SUPERVISOR GEORGE OLIVA

TO INVESTIGATE WORK WITHOUT PERMITS:

1. ON THE NW CORNER OF THE PROPERTY I FOUND A RECENTLY INSTALLED CHAINLINK FENCE ENCLOSURE.

NO PERMIT FOR DUMPSTER ENCLOSURE.

CASE NO: CE17020556
CASE ADDR: 1144 NW 4 AVE

OWNER: HIZUENGA 1144 LAND TR

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION

PURPOSES UNTIL APPROVED.

WORK REQUIRING PERMITS MUST BE INSPECTED.

CASE NO: CE17021488
CASE ADDR: 2131 NE 56 CT

OWNER: JLP REALTY OF FLORIDA LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER:

1. BATHROOMS AND KITCHENS REMODELED IN BOTH

UNITS.

2. NEW 3' SIDE DOORS INSTALLED.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS
REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE
BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK
SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION

PURPOSES UNTIL APPROVED.

CASE NO: CE17070861 CASE ADDR: 2251 NW 29 TER

OWNER: ROYAL 3 HOLDINGS LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BATHROOMS AND KITCHEN RENOVATION.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS
REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE
BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK
SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION

PURPOSES UNTIL APPROVED.

CASE NO: CE16062148

CASE ADDR: 1431 SW 32 CT

OWNER: SPAAPEN, JULES

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CARPORT CONVERTED INTO LIVING AREA.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16072241
CASE ADDR: 3110 SW 21 ST
OWNER: MAHMOOD, UNEEZA
RASHID, MAHOOD

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ROOF STRUCTURE REPAIRS REQUIRES ENGINEERING DRAWINGS.
- 2. NEW DRYWALL COVERINGS ON WALLS.
- 3. NEW DRYWALL ON CEILINGS.
- 4. REMODEL KITCHEN AND BATHROOMS.
- 5. COVERED OPENINGS FROM WALL A/C UNITS IN EXTERIOR WALLS.
- 6. ROOF STRUCTURE AT BACK ELEVATION OF CORRUGATED MATERIAL.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION FOR MECHANICAL A/C EQUIPMENT.
- 2. INSTALLATION OF MECHANICAL DUCT WORK.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. REPLACING DOORS AND WINDOWS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. NEW WATER SUPPLY LINES.
- 2. NEW WASTE LINES.
- 3. NEW BATHROOM AND KITCHEN FIXTURES.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. ISTALLING NEW WIRING CIRCUITS.
- 2. INSTALLING NEW RECEPTACLES.
- 3. INSTALLING NEW ELECTRICAL FIXTURES.
- 4. INSTALLING NEW WIRING CIRCUITS FOR MECHANICAL EQUIPMENT.
- 5. INSTALLING NEW BREAKER PANEL.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPE OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16080549

CASE ADDR: 5581 NE 28 AVE

OWNER: DESIMONE, MICHAEL

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTION OF WOOD DECK IN BACK YARD.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16080756 CASE ADDR: 200 NE 16 PL

OWNER: SQUIRES, TAHAUN DARNELL

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2010) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW CONCRETE CARPORT APRON.

2. NEW FRONT DOOR INSTALLED.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND

WINDOW PERMIT AND INSPECTIONS:
1. NEW FRONT DOOR INSTALLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16091583
CASE ADDR: 2140 SW 36 AV
OWNER: AGOSTINHO, MONICA
PIRES, MARCOS ANDRE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. NEW DRIVEWAY CONSTRUCTION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16101151 CASE ADDR: 2115 SE 18 ST

OWNER: BOAT HOUSE POOL INC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW DOCK INSTALLED.

FBC(2014) 105.3.1.4.1

THE ERECTION OR CONSTRUCTION OF ANY BUILDING OR STRUCTURE, THE ADDING TO, ENLARGING, REPAIRING, IMPROVING, ALTERING, COVERING OR EXTENDING OF ANY

BUILDING OR STRUCTURE.
1. NEW DOCK INSTALLED

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16101628
CASE ADDR: 805 SW 16 ST
OWNER: EIGHT O FIVE LLC
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:
1. BATHROOM RENOVATION.
2. BATHROOM ADDITION.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16110513

CASE ADDR: 1335 SEMINOLE DR

OWNER: BANK OF NEW YORK TRSTEE

% BAYVIEW LOAN SERVICING LLC

NEW OWNER: SLB ACQUISITIONS LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. MULTIPLE INTERIOR RENOVATIONS: A. DRYWALL FRAMING INSTALLATION.

B. KITCHEN REMODELING.C. BATHROOM REMODELING.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16121682
CASE ADDR: 1521 SW 4 AVE
OWNER: WILLIAMS, JOSIE
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW PAVER DRIVEWAY INSTALLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17020603

CASE ADDR: 601 N RIO VISTA BLVD OWNER: SOUTH BANK APTS LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. KITCHEN REMODELING.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION. INSPECTIONS PRESUMING TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION SHALL NOT BE VALID. IT SHALL BE THE DUTY OF THE PERMIT APPLICANT TO CAUSE THE WORK TO REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES. NEITHER THE BUILDING OFFICIAL NOR THE JURISDICTION SHALL BE LIABLE FOR EXPENSE ENTAILED IN THE REMOVAL OR REPLACEMENT OF ANY MATERIAL REQUIRED TO ALLOW INSPECTION.

CASE NO: CE17021124 CASE ADDR: 1701 SW 13 ST

OWNER: R O S INVESTMENTS LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW EXTERIOR WINDOWS AND DOORS INSTALLED.

2. CARPORT ENCLOSED.

- 3. KITCHEN REMODELED.
- 4. BATHROOM REMODELED.
- 5. NEW SEWER LINE INSTALLED FROM CARPORT TO EXISTING.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVER-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17032390
CASE ADDR: 2120 SW 28 TER
OWNER: PINEIRO, GUSTAVO

UNG, LENA

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. NEW PAVERS INSTALLED ON DRIVEWAY.

FBC(2014) 110.6

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION. INSPECTIONS PRESUMING TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION SHALL NOT BE VALID. IT SHALL BE THE DUTY OF THE PERMIT APPLICANT TO CAUSE THE WORK TO REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES. NEITHER THE BUILDING OFFICIAL NOR THE JURISDICTION SHALL BE LIABLE FOR EXPENSE ENTAILED IN THE REMOVAL OR REPLACEMENT OF ANY MATERIAL REQUIRED TO ALLOW INSPECTION.

CASE NO: CE17050281 CASE ADDR: 1416 NW 4 ST

OWNER: TRUST NO 1416 LAND TRUST SERVICE CO

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW WINDOW INSTALLED ON FRONT ELEVATION OF

PROPERTY.

FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR WINDOW ON FRONT ELEVATION.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION. INSPECTIONS PRESUMING TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION SHALL NOT BE VALID. IT SHALL BE THE DUTY OF THE PERMIT APPLICANT TO CAUSE THE WORK TO REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES. NEITHER THE BUILDING OFFICIAL NOR THE JURISDICTION SHALL BE LIABLE FOR EXPENSE ENTAILED IN THE REMOVAL OR REPLACEMENT OF ANY MATERIAL REQUIRED TO ALLOW INSPECTION.

CASE NO: CE17060394 CASE ADDR: 520 NE 8 AV

OWNER: CHABAD OF LAS OLAS INC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW STRUCTURE ADDED ON THE NORTH ELEVATION OF PROPERTY.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION. INSPECTIONS PRESUMING TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION SHALL NOT BE VALID. IT SHALL BE THE DUTY OF THE PERMIT APPLICANT TO CAUSE THE WORK TO REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES. NEITHER THE BUILDING OFFICIAL NOR THE JURISDICTION SHALL BE LIABLE FOR EXPENSE ENTAILED IN THE REMOVAL OR REPLACEMENT OF ANY MATERIAL REQUIRED TO ALLOW INSPECTION.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE08080683
CASE ADDR: 1538 NE 3 AVE
OWNER: TUCHOW, TYLER
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WINDOWS WERE INSTALLED.
- 2. DOORS WERE INSTALLED.
- 3. A FENCE WAS INSTALLED.
- 4. VINYL SIDING WAS INSTALLED.
- 5. INTERIOR ALTERATIONS AND DRYWALL WERE DONE.
- 6. KITCHEN AND BATH REMODELING HAVE BEEN DONE.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. A WASHER WAS INSTALLED.
- 2. PIPING AND FIXTURES HAVE BEEN INSTALLED FOR THE KITCHEN AND BATH REMODELING.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. CIRCUITS HAVE BEEN ADDED/ALTERED FOR WINDOW AND WALL A/C UNITS.
- 2. CIRCUITS HAVE BEEN ADDED/ALTERED FOR WASHER AND DRYER THAT WERE INSTALLED.
- 3. CIRCUITS HAVE BEEN ADDED/ALTERED FOR THE KITCHEN AND BATH REMODELING.
- 4. CIRCUITS HAVE BEEN ADDED/ALTERED IN THE GENERAL INTERIOR WORK BEING DONE.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. WALL AND WINDOW UNITS HAVE BEEN INSTALLED.

FBC(2007) 109.10

WORK HAS BEEN COVERED UP WITHOUT FIRST HAVING OBTAINED THE REQUIRED INSPECTION APPROVALS.

9-281 (a)

RUBBISH AND TRASH ARE LITTERING THE PREMISES. REMOVE TRASH AND DEBRIS.

CASE NO: CE16070373
CASE ADDR: 2610 SW 5 ST
OWNER: SRZMIAI LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

INTERIOR REMODELING.
 STRUCTURAL ALTERATIONS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

PLUMBING ALTERATIONS INCLUDING BUT NOT LIMITED TO:

1. INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

ELECTRICAL ALTERATIONS INCLUDING BUT NOT LIMITED TO:

1. INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING, ELECTRONIC MONITORING SYSTEMS, FIRE ALARMS, BURGLAR ALARMS AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16071180
CASE ADDR: 512 NW 15 TER
OWNER: PASCAL 2014 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE INTERIOR FLOOR PLAN CONFIGURATION OF THIS SINGLE FAMILY HOME HAS BEEN ALTERED.
- 2. KITCHEN HAS BEEN REMODELED.
- 3. BATHROOM HAS BEEN REMODELED.
- 4. BATHROOM HAS BEEN ADDED.
- 5. FRONT PORCH HAS BEEN BUILT AND ENCLOSED.
- 6. SECOND ACCESSORY STRUCTURE HAS BEEN BUILT AT BACK OF PARCEL AND CONVERTED TO A SECOND OCCUPIED RESIDENCE.
- 7. UTILITY LAUNDRY CLOSET BUILT AT BACK OF PRIMARY STRUCTURE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN KITCHENS AND BATHS.
- 2. INSTALLATION OF WATER SUPPLY AND WASTE LINES TO SERVICE BATHROOM ADDED, BATHROOM REMODEL LAUNDRY AND WATER HEATER.
- 3. INSTALLATION OF WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS TO SERVICE WATER HEATER, WASHER-DRYER, MECHANICAL SYSTEM, RECEPTACLES AND FIXTURES.
- 2. INSTALLATION OF RECEPTACLES.
- 3. INSTALLATION OF BREAKER PANEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE08070448
CASE ADDR: 1431 NW 11 PL
OWNER: DRAGOSLAVIC. G

DWNER: DRAGOSLAVIC, GORAN
DRAGOSLAVIC, TERESA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2007) 105.1

THE PROPERTY SUSTAINED MAJOR DAMAGE TO THE

STRUCTURE AND THE INTERIOR CAUSED BY A FIRE BACK

ON JULY 7, 2008.

A STOP WORK ORDER WAS ISSUED ON JULY 11, 2011 FOR WORK IN PROGRESS. ALL THE REPAIRS WERE PERFORMED

WITHOUT OBTAINING THE REQUIRED PERMITS AND

INSPECTIONS:

- 1. THE ELECTRICAL SYSTEM WAS DAMAGED AND IT HAS BEEN REPAIRED.
- 2. THE FAMILY ROOM CEILING RAFTERS WITH THE ROOF DECK WERE COMPLETELY BURNED AWAY. THEY HAVE BEEN REPLACED.
- 3. COMPLETE INTERIOR RESTORATION: ALL THE ELECTRICAL AND PLUMBING FIXTURES, THE DRYWALL ON THE CEILING AND WALLS, WITH ALL THE CABINETRY WERE REPLACED.
- 4. THE AIR CONDITIONING SYSTEM HAS BEEN REPLACED IN WHOLE OR IN PART FROM THE FIRE DAMAGE.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE11040091
CASE ADDR: 509 NW 20 AV
OWNER: RETLEY, LELA EST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. MOST OF THE WINDOWS AT THE DWELLING WERE REPLACED.
- AN EXTERIOR DOOR WAS REPLACED AT THE REAR OF THE PROPERTY

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE FAUCET FOR THE TUB, THE LAVATORY AND VANITY, AND THE TOILET WERE REPLACED IN THE BATHROOM.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE WINDOWS AND DOORS THAT HAVE BEEN INSTALLED DO NOT PROVIDE THE REQUIRED RESISTANCE TO THE IMPACT OF WINDBORNE DEBRIS. AN APPROVED SHUTTER SYSTEM HAS NOT BEEN PROVIDED.

CASE NO: CE16011458

CASE ADDR: 2307 N OCEAN BLVD OWNER: KERR-ROLLE, SWABY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

REMODELING OF STRUCTURE, INTERIOR AND EXTERIOR.

- 1. REMODELING INTERIOR WALL, REMOVING WALL COVERING AND REINSTALLING THROUGHOUT INCLUDING BATHROOMS, KITCHENS AND OTHER LIVING AREAS.
- 2. INSTALLED PERMANENT STRUCTURE ON EXTERIOR WALLS.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ADDING/ALTERING THE COOLING AND HEATING SYSTEM.
- 2. ALTERING KITCHEN AND BATHROOM EXHAUST SYSTEM.

FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH

AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF PLUMBING FIXTURES INCLUDING TOILETS, FAUCETS, PLUMBING LINES, VALVES, WASTE LINES. PLUMBING ASSOCIATED WITH BATHROOM AND KITCHEN REMODELING.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION AND REPLACEMENT OF FIXTURES, OUTLETS, SWITCHES, BREAKER PANELS AND DISCONNECTS.

FBC(2014) 105.3.1.5

SUBMIT DRAWINGS AND A SCOPE OF WORK COVERING STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC (2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY THE RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

ONSITE INSPECTION WILL BE REQUIRED TO VERIFY PERMIT APPLICATION REQUIREMENTS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF MULTI-FAMILY TO ASSIGNED LIVING FACILITY WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT

CASE NO: CE16020021

CASE ADDR: 6303 NW 9 AVE # 9

OWNER: 6303 L L C INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. WATER HEATER.
- 2. DINING ROOM SINK WITH FIXTURES.
- 3. ONE SMALL STAINLESS STEEL SINK AND ONE DOUBLE STAINLESS STEEL SINK WITH FIXTURES.
- 4. VANITY SINK WITH TOILET.

FBC(2014) 105.3.1.5

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

FBC(2014) 105.3.1.4.11

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. COMMERCIAL KITCHEN EXHAUST HOOD WITH FIRE SUPPRESSION SYSTEM.
- 2. TWO WALK-IN COMMERCIAL COOLERS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS TENANT SPACE HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF WALK-IN FOOD TAKE-OUT TO SIT DOWN RESTAURANT WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE16050226

CASE ADDR: 728 NW 6 AVE # A OWNER: CASALE, ROSANNE D

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FRAMED AND INSTALLED DRYWALL ON OFFICE ENCLOSURE IN THIS WAREHOUSE.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLED NEW ELECTRICAL CIRCUITRY AND FIXTURES, INCLUDING LOW VOLTAGE CIRCUITS. NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED SPLIT A/C MECHANICAL SYSTEM. NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050861
CASE ADDR: 2780 NW 24 CT
OWNER: 2771 LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FRONT ENTRANCE DOOR REPLACED.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. CENTRAL A/C REPLACED AND RELOCATED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16060517
CASE ADDR: 1042 NW 8 AV
OWNER: CM3 HOMES LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL

PERMIT AND INSPECTIONS:

1. NEW INSTALLATION OF 2 SPLIT CENTRAL A/C MECHANICAL SYSTEMS. COMPRESSOR FOR FRONT UNIT MANUFACTURED DATE MAY 2008. COMPRESSOR FOR REAR UNIT DATED JANUARY 2009.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF KITCHEN AND VANITY SINKS
- 2. NEW KITCHEN CABINETS AND VANITY CABINET.
- NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF RECEPTACLES ONE OVER THE KITCHEN SINK IS UNVERIFIED AS BEING IN GFI CIRCUIT. REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6), 210.8 (B) (5) SINKS AND 210.8 (B) (6) INDOOR WET LOCATIONS.
- NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16062293 CASE ADDR: 1716 SW 11 ST

OWNER: CONCESSION MANAGEMENT LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR ALTERATIONS INCLUDING NEW WALL AND

CEILING DRYWALL COVERING.
2. SHED IN THE BACKYARD.

Z. Shill in the Brokerak

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF FENCE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS.
- 2. INSTALLATION OF WASTELINES AND PLUMBING LINES IN KITCHEN, BATHROOMS AND LAUNDRY ROOM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF RECEPTACLES AND CIRCUITS IN THE KITCHEN.
- 2. INSTALLATION OF SUB-PANEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.4.8

THE FOLLOWING INSTALLATION REQUIRES A PERMIT:

1. INSTALLATION OF CANOPY AWNING IN BACKYARD.

FBC(2014) 110.6

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY
REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND
ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION
OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

CASE NO: CE17030615 CASE ADDR: 539 NE 14 PL

OWNER: LISA INVESTMENTS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:

1. INSTALLATION OF FENCE AND GATE.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS PARCEL AND BUILDING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF DUPLEX TO TRIPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

._____

CASE NO: CE16061700 CASE ADDR: 1553 NW 15 AVE

OWNER: 2771 LLC INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING. INSTALLATION OF WALL COVER IN WET SHOWER AREAS.
- 2. KITCHEN REMODEL, PERMIT WAS VOIDED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF PLUMBING FIXTURES, KITCHENS AND BATHROOMS.
- 2. REPLACED HOT WATER HEATER.
- 3. INSTALLATION OF WATER SUPPLY LINES IN LAUNDRY ROOM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF BREAKER CIRCUIT PANEL.
- 2. INSTALLATION OF RECEPTACLES.

REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6)

GFI REQUIRED AS PER NEC 108.8.

R314.3.1 WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. REPLACEMENT OF SPLIT A/C MECHANICAL SYSTEM.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16051422

CASE ADDR: 1249 SEABREEZE BLVD

OWNER:

MITTONE, HUGO F

MITTONE, PATRICIA N

INSPECTOR: JOSE ABIN

First heard 10/25/16 to comply by 2/28/17. 8 sections @ \$25 per day per violation. Order recorded. Not complied.

VIOLATIONS: FBC(2014) 105.1

Extensions:

2/28/17 - 4/25/17 4/25/17 - 6/27/17 6/27/17 - 10/24/17

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING INCLUDING KITCHEN AND BATHROOMS.
- 2. TILED WALL COVERINGS IN BATHROOMS AND KITCHENS INCLUDING BUT NOT LIMITED TO WET AREAS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WATER SUPPLY AND WASTE LINES.
- 2. INSTALLATION OF BATHROOM AND KITCHEN FIXTURES NOT LIMITED TO SINKS, FAUCETS, VANITIES, TOILETS AND BIDETS.
- 3. INSTALLATION OF WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS.
- 2. INSTALLATION OF ELECTRICAL FIXTURES.
- 3. INSTALLATION OF BREAKER PANELS.
- 4. INSTALLATION OF NEW LIGHTING.
- 5. INSTALLATION OF NEW RECEPTACLES.

REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4

(D) (1) THRU (D) (6)

GFI'S REQUIRED AS PER NEC 108.8

OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK AND REGISTERS.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLATION AND REPLACEMENT OF DOORS AND WINDOWS.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16070025

CASE ADDR: 401 RIVIERA ISLE #503 OWNER: BROOKS, CHRISTOPHER

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS, DEMOLITION AND REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE INCLUDING AN ELECTRICAL PANEL REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE13080252

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR RENOVATIONS.

FBC(2010) 105.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM IS BEING ALTERED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE13091180 CASE ADDR: 833 NW 19 AV

OWNER: BROWN, J M & SILLIE MAE EST

NEW OWNERS: MCCLAIM, KIMBERLY

JONES, AUDREY

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. WINDOWS AND DOORS ARE BEING REPLACED.
- 2. A/C UNIT WAS REPLACED.
- 3. ELECTRICAL WORK DONE. DISCONNECTED BOX TO THE A/C.
- 4. PLUMBING WORK DONE. A DRAIN LINE WAS EXPOSED ON THE NORTH SIDE OF THE HOUSE DRAINING ONTO THE GROUND.

FBC(2010) 105.4.4

PLUMBING INSTALLED AND EXPOSED ON NORTH SIDE OF HOUSE AND DRAINING ONTO THE GROUND WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.5

ELECTRICAL WORK INSTALLED, DISCONNECT TO A/C WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.15

WINDOWS AND DOORS INSTALLED WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

CASE NO: CE15102509

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS COMMERCIAL SPACE HAS BEEN COMPLETELY
REMODELED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL INSTALLED WITHOUT THE
REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS COMMERCIAL OFFICE SPACE AND THE ADJOINING UNITS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120540

CASE ADDR: 3024 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL, REBUILDING EXTERIOR STAIRS AND DECKS, AND REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING COMPLETELY REMODELED AND REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16101617

CASE ADDR: 2436 OKEECHOBEE LN

OWNER: FUNG YOUNG, RICARDO ALONSO

GLANERT, CLEONICE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. SWIMMING POOL AND POOL DECK BEING BUILT THAT ARE NOT IN ACCORDANCE WITH THE APPROVED PLANS. THE SCOPE OF WORK HAS EXCEEDED THE PREVIOUS APPROVED PLANS THAT WERE ISSUED.
- 2. THE MASTER POOL PERMIT 15111202 HAS NOW EXPIRED AND THE PERMIT IS NOW POTENTIALLY NULL AND VOID. THE POOL HAS NOT PASSED THE REQUIRED INSPECTIONS AND THE MAJORITY OF THE WORK IS COMPLETED, THE POOL IS FILLED AND BEING USED. THIS POOL IS NOW CONSIDERED AN UNSAFE STRUCTURE AND POSES A POTENTIAL LIFE SAFETY ISSUE.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE16111730
CASE ADDR: 1779 SE 25 AV
OWNER: MIADO LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INTERIOR DEMOLITION OF THE KITCHEN,
BATHROOMS, INTERIOR WALLS AND A COMPLETE INTERIOR
RENOVATION IN PROGRESS INCLUDING STRUCTURAL,
ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED
PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16030934 CASE ADDR: 3334 NE 32 ST

OWNER: NORTH BEACH PROPERTY INVESTMENTS LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. INTERIOR ALTERATIONS MADE SUCH AS FRAMING, DRYWALL, ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 2. THE BUSINESS OPERATION AT THIS PROPERTY MAY ALSO REQUIRE A CHANGE OF USE.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY

CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE16061714

CASE ADDR: 1400 NE 56 ST # 209
OWNER: DIXIE REALTY LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE TO THE KITCHEN AND BATHROOM
BEING FULLY REMODELED INCLUDING FRAMING AND DRYWALL
WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE TO THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE TO THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 109.3.3

THE PROPERTY/CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

CASE NO: CE16031237 CASE ADDR: 500 NE 13 ST

OWNER: ALSARRA GROUP LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INSTALLED NEW TOILETS, SINKS, VANITIES AND FIXTURES.
- 2. INSTALLED NEW ELECTRICAL WIRING, OULETS.
- 3. INSTALLED NEW A/C WINDOWS UNITS.
- 4. CONSTRUCTED NEW BLOCK WALLS.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING, ELECTRONIC MONITORING SYSTEMS, FIRE ALARMS, BURGLAR ALARMS AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS ISSUED AFTER WORK HAS COMMENCED, AFTER THE FACT, TO BE DOUBLE FEE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15080754
CASE ADDR: 1706 NW 14 CT
OWNER: TUCHOW, TYLER
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. GARAGE WAS CONVERTED INTO LIVING SPACE.
- 2. CONSTRUCTION OF A SECOND BATHROOM.
- 3. AIR CONDITIONING SYSTEM CHANGE OUT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16041977
CASE ADDR: 1511 NW 11 PL
OWNER: 2771 LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THE STRUCTURES ON THIS PROPERTY HAVE BEEN ALTERED WITHOUT PERMIT IN THE FOLLOWING MANNER:

- 1. WINDOWS AND EXTERIOR DOORS HAVE BEEN REPLACED.
- 2. GLASS BLOCK HAS BEEN INSTALLED IN PLACE OF THE BATHROOM WINDOW.
- 3. NEW SINK AND TOILET INSTALLED IN THE BATHROOM.
- 4. THE KITCHEN HAS BEEN REMODELED WITH ELECTRICAL OUTLETS AND DISHWASHER ADDED. KITCHEN SINK REPLACED.
- 5. THE WATER HEATER HAS BEEN REPLACED.
- 6. PLUMBING AND ELECTRICAL HAS BEEN ADDED FOR A WASHER AND DRYER IN THE UTILITY ROOM.

- 7. A CENTRAL A/C SYSTEM HAS BEEN INSTALLED.
- 8. ELECTRICAL SERVICE HAS BEEN UPGRADED WITH AN OUTSIDE BREAKER PANEL.
- 9. THE SHED DOOR HAS BEEN REPLACED.

10. A WOOD FENCE IS INSTALLED ON THE WEST SIDE OF THE HOUSE.

CASE NO: CE16070231

CASE ADDR: 500 E DAYTON CIR

OWNER: ISLANDER'S HOMES INVESTMENT LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM RENOVATIONS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16081896 CASE ADDR: 1213 NW 4 AV

OWNER: BRIDGE GLOBAL INC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW FRONT DOOR AND EXTERIOR WINDOWS INSTALLED.

FBC(2014) 105.3.1.4.15

THE INSTALLATION OF EXTERIOR WINDOWS AND EXTERIOR GLASS DOORS IN NEW BUILDINGS OR ADDITIONS AND THE INSTALLATION, ALTERATION OR REPAIR OF SUCH WINDOWS AND DOORS IN EXISTING BUILDINGS REQUIRES PERMITS.

1. NEW EXTERIOR WINDOWS AND FRONT DOOR HAVE BEEN INSTALLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16090813 CASE ADDR: 914 SE 2 CT

OWNER: MOORMAN PROPERTIES III LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. NEW WOOD STRUCTURE WITH ROOF INSTALLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16120039
CASE ADDR: 1320 NE 7 AVE

OWNER: 1320 NE 7TH AVE LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CONSTRUCTION OF DUMPSTER ENCLOSURE.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED. APPROVAL AS A RESULT OF AN INSPECTION SHALL NOT BE CONSTRUED TO BE AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION. INSPECTIONS PRESUMING TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION SHALL NOT BE VALID. IT SHALL BE THE DUTY OF THE PERMIT APPLICANT TO CAUSE THE WORK TO REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES. NEITHER THE BUILDING OFFICIAL NOR THE JURISDICTION SHALL BE LIABLE FOR EXPENSE ENTAILED IN THE REMOVAL OR REPLACEMENT OF ANY MATERIAL REQUIRED TO ALLOW INSPECTION.

CASE NO: CE16121184
CASE ADDR: 2470 NW 16 ST

OWNER: ROBINSON, LEON MYRON H/E

ROBINSON, REGENIA

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ALTERATION OF WINDOW OPENINGS.

2. REPLACEMENT OF WINDOWS.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16121633
CASE ADDR: 2201 NE 16 ST
OWNER: EDWARDS, ANDY L
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW PAVER DRIVEWAY AND CONCRETE GARDEN WALLS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17020045 CASE ADDR: 721 SW 2 ST

OWNER: FREE BETHLEHEM BAPTIST CHURCH INC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED:

1. PAVING AND RESURFACING PARKING AREA.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17020841
CASE ADDR: 1220 SE 2 ST
OWNER: BLUDWORTH, TODD
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:
1. KITCHEN RENOVATION.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17060231
CASE ADDR: 1112 NE 5 AVE

OWNER: HENAO INVESTMENTS LLC

INSPECTOR: ROBERT KISAREWICH

VIOLATIONS: NFPA 101:30.3.5.1

THE BUILDING IS NOT PROVIDED WITH THE REQUIRED FIRE

SPRINKLER SYSTEM.

NFPA 101:43.7.2

THE STRUCTURE HAS EXPERIENCED A CHANGE IN THE OCCUPANCY

CLASSIFICATION.

NFPA 101:30.1.7

AN APPROVED OCCUPANT LOAD IS NOT PROVIDED OR IS EXCEEDED.

NFPA 101:30.2.1.2

A MEANS OF ESCAPE IS NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 101:30.3.4.5

SMOKE ALARMS ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 1:13.6.2

FIRE EXTINGUISHER(S) IS/ARE NOT PROVIDED IN ACCORDANCE WITH THE CODE.

NFPA 101:30.3.2.1.1

THE PROPER FIRE RATINGS ARE NOT PROVIDED FOR HAZARDOUS AREAS.

CASE NO: CE16120832 CASE ADDR: 2849 SW 4 CT

OWNER: NOARALIS, VERISSEAU

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WINDOW REPLACEMENTS.

2. WOOD FENCE INSTALLATION.

3. STUCCO INSTALLATION ON SOFFITS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17021674 CASE ADDR: 648 NE 17 AVE

OWNER: 648 NE 17TH AVE LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. THE INTERIOR OF THIS BUILDING HAS BEEN

DEMOLISHED, TO INCLUDE BUT NOT LIMITED TO DYWALL, FRAMING, ELECTRICAL, PLUMBING, A/C DUCTS ETC.

FBC(2014) 110.1

GENERAL CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTION BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION

PURPOSES UNTIL APPROVED.